

L-410 UVP-E - Normal checklist

NORMAL CHECKLIST

ATIS PRATIA: 122,15 - PŘEDEM:

DESCENT		DESCENT CLEARANCE
Transparent	ON	PNF
Taxi light 10000 ft	ON	PNF
Emergency exit	CKD	F/O
ATIS	RECEIVED	PNF
Approach briefing		ALL
Radioaltimeter	SET.....	C

BLOCKS	
Parking brakes	SET F/O
Taxi lights	OFF F/O
Prop.levers	FEATHER F/O
Overhead panel	OFF F/O
Generators	OFF F/O
Fuel shutoff lev.	SHUTOFF F/O
Escon	OFF F/O
Fuel boost pumps	OFF F/O
Fuel control lev.	CLOSED F/O
Battery	OFF F/O

APPROACH		APPROACH CLEARANCE
Altimeters	SET...XCKD	ALL
Compasses	SET...FOR LAND	ALL
VOR, ILS, DME, ADF	FOR LAND	ALL
Autofeath., bank, spoil.	ON	PNF
Nose gear stear.	PEDALS	PNF
Antiskid	ON	PNF
Reverse latch	OPEN	PNF

REPORT OF ESTABLISHING → LANDING CLEARANCE

LANDING		max 250
Gear	DOWN, 3 GREEN	PNF
Flaps	18	PNF
Heating	CLOSED	PNF
Landing lights	ON	PNF

Flaps 42° - max 220 km/h.
PRATIA VYCHLOST - min. 180 km/h
např. 250 km/h

AFTER LANDING		REPORT VACATED +
Transponder	OFF	F/O
Flaps	ZERO	F/O
Taxi lights	ON	F/O
Anti-ice group	OFF	F/O
Autofeath., bank, spoil.	OFF	F/O
VOR, ILS, DME, ADF	OFF	F/O
Stby horizon	DET	F/O
Horizons	OFF	ALL
Inv. 36V II, 115V I, II.	OFF	F/O
Time	CKD	F/O

TAXI INSTRUCTIONS.