

STANDARD ARRIVAL ROUTES - INSTRUMENT (STAR) RNAV (RNP) GNSS RWY 05/23

STAR	ROUTING	ALTITUDES
LISA 1A	LISA ONE ALFA After passing LISA proceed to LS, then proceed to IAF_S	Cross LISA at or above FL150, passing LS at or above FL120, over IAF_S 9200'
LISA 1B	LISA ONE BRAVO After passing LISA proceed to LS, then proceed to IAF_N (DVOR/DME SPT)	Cross LISA at or above FL150, passing LS at or above FL120, over IAF_N (DVOR/DME SPT) at 6600'
LISA 1C	LISA ONE CHARLIE After passing LISA proceed to D19km/R-242 ⁰ SPT, then proceed to IAF_N (DVOR/DME SPT)	Cross LISA at or above FL150, passing D19km/R-242 ⁰ SPT at or above FL120, over IAF_N (DVOR/DME SPT) at 6600'
SAVI 1A	SAVI ONE ALFA After passing SAVI proceed to D22km/R-273 ⁰ SPT, then proceed to IAF_N (DVOR/DME SPT)	Cross SAVI at or above FL150, passing D22km/R-273 ⁰ SPT at or above FL120, over IAF_N (DVOR/DME SPT) at 6600'