

VISUAL DEPARTURE ROUTES - RWY 05

DEPARTURE RWY 05

Climb STRAIGHT AHEAD to SPT R-054° D6.5 km at or above 3000', turn LEFT to SPT DVOR/DME at or above 6600'. After passing SPT DVOR/DME, turn RIGHT on 053° track and on RACETRACK procedure climb to SPT DVOR/DME at FL120 or above. Leaving SPT DVOR/DME for NDB LS only at FL120 or above. Cross NDB LS at FL140 or above.

CAUTION

Take-off and flight up to FL90 only in accordance with VFR. Max IAS 300 km/h bank 25°.